

METALOCK International


Ülkü Gürkan

BİLUMUM METALOCK TAMİRATI
GEMİ MAKİNA YAN SANAYİ İMALATI

Tarih /.... /200....

MV PACIFIC VICTOR
MAN – HENAN DIESEL ENGINE INDUSTRY
CO.LTD. P.R.C
TYPE:6L 16/24 CFB
SERIAL NO: 6A6C00065/66/67
DAMAGED D/G CYL.BLOCK REPAIR WITH
METALOCK

REPAIRED REPORT



It was determined damaged area.



It was cutted damaged area to outside.



It was made new cast iron instead of damaged area. (GGG 40)



New cast iron was putted on area that cutted.



New cast iron was made metalock.



New cast iron was made metallock.



The work was completed by grinding.